


WR85

Place screw here to lock plug when tuned.



Make plug a slip fit into rectangular tube. Need to move it back and forth tuning the distance to the connector center probe then solder it in place. Would like to keep face of plug as close to perpendicular to side walls as possible.

Screw hole in back of plug is for adjustment.